

# **Home Report**



# **33C Grosvenor Place,** Aberdeen, AB25 2RE



### 33C Grosvenor Place,

Aberdeen, AB25 2RE

Price Over

£115,000













Council tax band B





Peterkins (Property Sales) 100 Union Street Aberdeen AB10 1QR

01224 428100

propcen@peterkins.com

http://www.peterkins.com









**Features** 



On street parking

## **Description**

Early viewing is essential to appreciate the interior of this appealing **two bedroom top floor** apartment which forms part of a traditional granite building within a prime West End location. The property has recently been refurbished to a high standard with fresh décor complimented by quality blinds and floor coverings. The accommodation comprises of: Entrance hallway; open plan living room and breakfast kitchen; two double bedrooms; bathroom with an over bath shower. Outside there is ample on street permit parking available on Grosvenor Place, residents can apply for a permit through Aberdeen City Council. The property benefits from a security entry system, gas central heating and double glazing.

- Appealing Two Bedroom Top Floor Apartment
- Open Plan Living Room & Breakfast Kitchen
- Two Double Bedrooms
- Attractive Bathroom with an Over Bath Shower
- Gas Central Heating

- Double Glazing
- Security Entry System
- On Street Permit Parking

**Location** Grosvenor Place is a popular tree-lined street in the heart of the city's fashionable West End. Both the City Centre and Rosemount are within walking distance of the property. The area offers a wide range of business, shopping and recreational facilities. Local convenience stores are available and there is a regular bus service to and from the City Centre. The Grammar School is located within a two-minute walk of the proper and there are also reputable nurseries and primary schools in the area.

#### **Directions**

From the West End of Union Street turn right onto Rose Street and continue straight ahead at the traffic lights onto Esslemont Avenue. Continue and turn first left onto Whitehall Place and first right into Grosvenor Place. Number 33C is situated on the left as indicated by our "For Sale" sign.



## **Accommodation comprises**

**Entrance:** A traditional hardwood exterior door with glazed side panels leads to the shared entrance; ceiling cornice; downlighter; hardwearing carpet; further door gives access to the internal communal stairwell which leads up to the first and second floors.

**Hallway:** A part glazed exterior door gives access to the property; wall light; radiator; a carpeted staircase with handrail leads up to the centrally positioned hallway with all accommodation leading off; wall mounted door entry handset; built-in cupboard housing the new central heating boiler; "Hive" central heating controls; consumer unit; smoke detector; fitted carpet.

**Living Room/Breakfast Kitchen:** 7.05m x 2.62m (23'2" x 8'7") approx. at widest points. The stylish living area has a large window to the rear of the property fitted with a roller blind; feature panelled wall; radiator; downlighters; laminate flooring.

The modern and well equipped kitchen is fitted with a excellent range of light grey high gloss base and wall mounted cabinets; "Silestone" work surfaces and upstands; breakfast bar; gas hob with a cooker hood extractor above; integrated appliances, oven, microwave, fridge/freezer, washing machine and

dishwasher; double window to the rear of the apartment fitted with a roller blind; heat detector; downlighters; laminate flooring.

**Bedroom 1:** 3.04m x 3.02m (10'0" x 9'11") approx. Bright and airy double bedroom with a front aspect; double window fitted with a roller blind; feature panelled wall; ample space for free standing furniture; radiator; downlighters; fitted carpet.

**Bedroom 2:** 3.14m x 3.04m (10'4" x 10'0") approx. Well appointed second double bedroom with a double window fitted with a roller blind overlooking the front of the property; built-in wardrobe with sliding doors providing great hanging and storage space; radiator; downlighters; laminate flooring.

**Bathroom:** Attractive, fully tiled, bathroom fitted with a white three-piece suite comprising of: W.C. with a concealed cistern, wash hand basin set onto a vanity unit and bath with an overhead mixer shower and glass shower screen; wall mounted mirrored medicine cabinet; chrome ladder style radiator; extractor fan; downlighters; under floor heating; tiled floor.


#### (Outside)

There is ample on street permit parking available on Grosvenor Place. Residents can apply for a permit from Aberdeen City Council for which an annual charge is applicable.

#### (Other Information)

The fitted flooring, light fittings, blinds and curtains will be included in the sale.

# **Photo gallery**



#### View this property on aspc.co.uk:

https://www.aspc.co.uk/search/property/434512/33C-Grosvenor-Place/Aberdeen/


The foregoing particulars are being distributed on behalf of the Selling Solicitors by Aberdeen Solicitors' Property Centre Ltd. of 2-10 Holburn Street, Aberdeen, AB10 6BT. Whilst the particulars have been prepared with care and are believed to be accurate, no liability for any errors or omissions therein or the consequences thereof will be accepted by the Selling Solicitors or Aberdeen Solicitors' Property Centre Ltd. © Aberdeen Solicitors' Property Centre and Selling Solicitors.

## **Broadband speed**



You can get up to 1800 Mbps average speed at this postcode.

### Mobile coverage



## **Ofcom**

This information is a prediction and actual services may be different depending on my circumstances and precise location. Provided by Ofcom, last retrieved on 16/05/2025. 5G coverage is not included in this data.

The data displayed on broadband coverage availability uses source data from Ofcom. The predicted speeds provided in the API data are provided by the leading UK ISPs. We understand that Ofcom did not receive data for every premise in the UK, and that Ofcom continue to work with industry to fill in the gaps. If no predictions are shown for your address, this does not necessarily mean broadband is not available and we suggest that you check availability on the ISP websites.

The data displayed on mobile coverage availability uses source data made available by Ofcom which is based on data from the mobile operators about how strong they think signal levels are at every location in the UK. Each mobile operator has a slightly different approach to displaying coverage on its own map, including assumptions on the handsets used, levels of call reliability and the expected signal loss when indoors or in car. Because Ofcom brings all mobile operator data together in a single place and holds it to a single, independent standard, the mobile coverage availability information above may display different levels of coverage than those seen on the operators' websites. We would therefore recommend you also check the mobile provider's coverage checker. Mobile coverage data is created by coverage modelling, and since this is based on computer predictions is not error free.

Ofcom update the source data regularly (every month) and the mobile network operators update theirs, but there may be times when the maps are based on slightly different data and therefore show different coverage.

For further information about the Ofcom APIs, read their FAQs available here.

https://www.ofcom.org.uk/siteassets/resources/documents/research-and-data/broadband-research/api-faqs?v=323603

# Property Questionnaire

PROPERTY ADDRESS:	33C Grosvenor Place Aberdeen AB25 2RE
SELLER(S):	Andrew Buchan
COMPLETION DATE OF PROPERTY QUESTIONNAIRE:	23/04/25

#### PROPERTY QUESTIONNAIRE

#### **NOTE FOR SELLERS**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

# PROPERTY QUESTIONNAIRE

Information to be given to prospective buyer(s)

1.	Length of ownership							
	How long have you owned the property? Since 2001							
2.	Council Tax							
	Which Council Tax band is your property in?							
	A B C D E F G H							
3.	Parking	-						
	<ul> <li>What are the arrangements for parking at your property?</li> <li>On street</li> <li>Resident permit</li> <li>Metered parking</li> </ul>							
4.	Conservation Area							
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?							
5.	Listed Buildings							
	Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	No						

6.	Alterations / additions / extensions					
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes				
	If you have answered yes, please describe the changes which you have made:					
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?					
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.					
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.					
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	No				
	If you have answered yes, please answer the three questions below:					
	(i) Were the replacements the same shape and type as the ones you replaced?	NA				
	(ii) Did this work involve any changes to the window or door openings?	NA				
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):					

Please give any guarantees which you received for this work to your solicitor or estate agent.

# 7. Central heating

a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).  If you have answered yes/partial – what kind of central heating is there?  gas-fired combi boiler	Yes
b.	When was your central heating system or partial central heating system installed?  Within the last three years	
C.	Do you have a maintenance contract for the central heating system?  If you have answered yes, please give details of the company with which you have a maintenance agreement:	No
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes

9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	No
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	NA
b.	Are you aware of the existence of asbestos in your property?  If you have answered yes, please give details:	No
4.0		

#### 10. Services

a. Please tick which services are connected to your property and give details of the supplier:

Services	Connected	Supplier
Gas / liquid petroleum gas	Yes	
Water mains / private water supply	Yes	
Electricity	Yes	
Mains drainage	Yes	
Telephone	Yes	
Cable TV / satellite	No	
Broadband		

b.	Is there a septic tank system at your property?	No
	If you have answered yes, please answer the two questions below:	
C.	Do you have appropriate consents for the discharge from your septic tank?	NA
d.	Do you have a maintenance contract for your septic tank?  If you have answered yes, please give details of the company with which you have a maintenance contract:	NA
11.	Responsibilities for Shared or Common Areas	

a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?  If you have answered yes, please give details:  Front Garden Area	Yes
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  If you have answered yes, please give details:  The main roof is shared by Flats A, B and C	Yes
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?  Flat roof was replaced in 2015	Yes
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?  If you have answered yes, please give details:	No

e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?  If you have answered yes, please give details:	No
f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)  If you have answered yes, please give details:	No
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?  If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:	No
b.	Is there a common buildings insurance policy?	No
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	NA
c.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	
13.	Specialist Works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?  If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property  Bay window and alcove joist end and floor boards were replaced 2001	Yes

b.	As far as you are aware, he dry rot, wet rot, or damp of property?		-					Yes	
	If you have answered yes, please give details								
	Yes floor boards were tre	ated in	า 200	1					
C.	If you have answered yes any guarantees relating to				o yo	u have		No	
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.  Guarantees are held by:								
14.	Guarantees								
a.	Are there any guarantees following:	or wa	rrant	ies fo	r any	of the			
(i)	Electrical work	No							
(ii)	Roofing	No							
(iii)	Central heating	No							
(iv)	NHBC	No							
(v)	Damp course	No							
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No							
b.	If you have answered 'yes of the work or installation								

C.	Are there any outstanding claims under any of the guarantees listed above?  If you have answered yes, please give details:	No
15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years?  If you have answered yes, please give details:	No
16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	No
b.	that affects your property in some other way?	No
C.	that requires you to do any maintenance, repairs or improvements to your property?	No
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.	

Declaration by the seller(s)/or other authorised body or person(s):

I confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature : Andrew Buchan

Date: 23-04-25

# survey report on:

Property address	Flat C, 33 Grosvenor Place, Aberdeen, AB25 2RE
Customer	Mr Andrew Buchan
Customer address	1 Belvidere Street, Aberdeen, AB25 2QS
,	
Prepared by	Allied Surveyors Scotland Ltd
Date of inspection	23rd April 2025



#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
  or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a flat on the top floor of a three storey block containing three flats in total.
Accommodation	Top floor: hallway, lounge with kitchen on open plan, two bedrooms, bathroom.
Gross internal floor area (m²)	47 square metres approximately.
Neighbourhood and location	The property is located within an established residential area a short distance from Aberdeen city centre where a good range of facilities and amenities can be found.
Age	125 years approximately.
Weather	It was dry and bright at the time of our inspection. The report should be read in the context of these weather conditions.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The chimney stacks are of stone construction that is pointed externally.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.

Roofing including roof space	The roof is of pitched timber frame design and clad with slates. No access was gained to any roof void. There are flat roof coverings over the dormer windows.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The rainwater fittings are of PVC and cast iron construction.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of stone construction that is pointed externally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are PVC and double glazed with the flat door being timber.
External decorations	Visually inspected.
Conservatories / porches	None.
Communal areas	Circulation areas visually inspected.
	Communal entrance hallway and stairwell providing access to all of the flats. Shared front garden.
Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually inspected.
	Shared front garden.
Ceilings	Visually inspected from floor level.
	The ceilings are of plasterboard construction.
1	•

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The walls are of plasterboard construction.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	The floors are of suspended timber construction. No access was gained to any sub-floor area.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	There is a good range of modern kitchen units.
Chimney breasts and fireplaces	None.
Internal decorations	Visually inspected.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Mains electricity is connected. The electrical apparatus is located within the hallway.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Mains gas is connected.
Water plumbing betherow fittings	
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains water is connected. There is a three piece bathroom suite.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a gas fired central heating system installed. This is supplied by a Worcester condensing boiler located in the hallway cupboard. Heating is supplied via panel radiators which have thermostatic valves.
Drainage	David and the state of the stat
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Mains drainage is connected.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	There are smoke alarms within the property.
	Legislation in respect of fire detection and carbon monoxide alarms has been introduced by the Scottish government, effective from February 2022. It is beyond the scope of this inspection to determine whether the property is compliant. Purchasers should confirm the requirements of the legislation and engage with qualified contractors, where appropriate.
Any additional limits to inspection	For flats / mais another
Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection

inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

#### Any additional limits to inspection

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

The property was fully furnished and had fitted floor coverings; therefore, no detailed inspection was possible of the floors and accordingly, no comment can be made on their condition. Internal cupboards were generally filled with storage items. No access was available beneath sanitary or kitchen fittings.


It was not possible to inspect the cold water rising main.

Not all of the windows were tested at the time of our inspection.

No sight of the flat roof coverings was possible.

The property questionnaire was not seen.

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5 Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- (17) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- (24) Chimney breast
- (25) Window pointing
  - Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 3) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	There is no evidence of any significant structural movement having taken place within the property.

Dampness, rot and infestation		
Repair category	1	
Notes	There is no evidence of any dampness, rot or infestation within the property.	

Chimney stacks	
Repair category	1
Notes	No significant defects were evident.

Roofing including roof space		
Repair category	2	
Notes	The roof is clad with slates. Natural slates have a lifespan which is dependent upon the type and quality of the slate. Over the long-term slates may deteriorate, their nail fixings may corrode, and the timber sarking boards may deteriorate particularly where exposed to penetrating moisture or condensation. Ongoing roof maintenance will be required, including keeping valley gutters clear of debris and monitoring the condition of the roof slates, metal flashings/valleys, and roof cement work, with a view to longer term re-slating.  There is a flat roof area over the dormer windows. Flat roofs have a limited life and depending on their age and quality of workmanship can fail at any time.  Roofs are prone to water penetration during adverse weather, but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs	

Roofing including roof space	
Repair category	2
Notes	should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.

Rainwater fittings	
Repair category	1
Notes	No significant defects were evident. Rainwater goods are best checked during periods of heavy rainfall.

Main walls	
Repair category	1
Notes	No significant defects were evident.

Windows, external doors and joinery	
Repair category	1
Notes	No significant defects were evident.

External decorations	
Repair category	1
Notes	No significant defects were evident.

Conservatories/porches	
Repair category	-
Notes	None.

Communal areas	
Repair category	1
Notes	No significant defects were evident.

Garages and permanent outbuildings	
Repair category	-
Notes	None.

Outside areas and boundaries	
Repair category	1
Notes	No significant defects were evident.

Ceilings	
Repair category	1
Notes	A stain was noted in the ceiling of the lounge. This was dry at the time of our inspection and we have assumed that the cause has been ascertained and rectified.

Internal walls	
Repair category	1
Notes	No significant defects were evident.

Floors including sub-floors	
Repair category	1
Notes	No significant defects were evident.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant defects were evident.

Chimney breasts and fireplaces	
Repair category	-
Notes	None.

Internal decorations	
Repair category	1
Notes	The standard of decoration was found to be good.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	1
Notes	No significant defects were evident. It is recommended good practice that all electrical installations are periodically checked, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.

<b>d</b> Gas	
Repair category	1
Notes	No significant defects were evident. In the interests of safety and in light of recent regulations we would recommend that all gas appliances are tested on an annual basis by a Gas Safe registered contractor.

Water, plumbing and bathroom fittings	
Repair category	2
Notes	Attention is required to the sealant and grouting at the bath. Wear and tear was noted to the wash hand basin vanity unit.

Heating and hot water	
Repair category	1
Notes	No significant defects were evident. It is common practice for incoming purchasers to have the central heating system tested upon taking occupation.

Drainage	
Repair category	1
Notes	No significant defects were evident.

# Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

# Single Survey

## 3. Accessibility information

### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Top floor.
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

# Single Survey

### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

We have assumed that external maintenance is split on an equitable basis.

Where items of repair have been identified, any purchaser should, prior to purchase, satisfy themselves as to the cost and implications of these issues.

Estimated reinstatement cost for insurance purposes	
£200,000.	

#### Valuation and market comments

The valuation takes into account recent sales transactions and current market trends.

£130,000 (ONE HUNDRED AND THIRTY THOUSAND POUNDS)

Signed	Security Print Code [542123= 5253] Electronically signed
Report author	Gordon Gibb
Company name	Allied Surveyors Scotland Ltd
Address	Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE
Date of report	24th April 2025



Property Address	
Address Seller's Name Date of Inspection	Flat C, 33 Grosvenor Place, Aberdeen, AB25 2RE Mr Andrew Buchan 23rd April 2025
<b>Property Details</b>	
Property Type	House       Bungalow       Chalet       Purpose built maisonette         Coach       Studio       Converted maisonette       X Purpose built flat         Converted flat       Tenement flat       Flat over non-residential use       Other (specify in General Remarks)
Property Style	□ Detached       □ Semi detached       □ Mid terrace       □ End terrace         □ Back to back       □ High rise block       ▼ Low rise block       □ Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	elieve that the property was built for the public sector, Yes X No nilitary, police?
Flats/Maisonettes on	y Floor(s) on which located Top No. of floors in block 3 Lift provided? Yes X No No. of units in block 3
Approximate Year of	Construction 1900
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 0 WC(s) 0 Other (Specify in General remarks)
Gross Floor Area (ex	cluding garages and outbuildings) 47 m² (Internal) m² (External)
Residential Element (	(greater than 40%) X Yes No
Garage / Parking /	Outbuildings
Single garage Available on site?	□ Double garage       □ Parking space         □ Yes       □ No             X No garage / garage space / parking space
Permanent outbuildin	igs:

Construction								
Walls	Brick	X Stone		oncrete	Timber frame			
	Solid	Cavity		eel frame	Concrete block	Othe	er (specify in Ger	neral Remarks)
Roof	Tile	X Slate		sphalt	Felt		()	,
	Lead	Zinc		tificial slate	Flat glass fibre	Othe	er (specify in Ger	neral Remarks)
	_	<u>—</u>				_		
Special Risks								
Has the property s	suffered struct	ural moveme	ent?				Yes	X No
If Yes, is this rece	nt or progress	ive?					Yes	No
Is there evidence, immediate vicinity	history, or rea?	ason to antic	ipate subs	sidence, he	eave, landslip o	or flood in th	e Yes	X No
If Yes to any of the	e above, prov	ide details in	General F	Remarks.				
Service Connec	tion							
Based on visual ir of the supply in Go			ces appea	ır to be noı	n-mains, pleas	e comment	on the type a	nd location
Drainage	X Mains	Private	None		Water	X Mains	Private	None
Electricity	X Mains	Private	None		Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None					
Brief description o	f Central Hea	ting:						
Gas fired system	1.							
Site								
Apparent legal iss	ues to be veri	fied by the c	onvevance	er. Please	provide a brief	description	in General R	emarks.
Rights of way	Shared drive	-	_		enities on separate	_	ared service con	
Agricultural land in	 cluded with prope	erty		ed boundarie	•		er (specify in Ge	neral Remarks)
Location								
Residential suburb	X Res	idential within to	own / city	Mixed re	sidential / comme	rcial Mai	inly commercial	
Commuter village		note village	on, only		rural property		er (specify in Ge	neral Remarks)
Planning Issues	<b>;</b>							
Has the property b	peen extended	d / converted	/ altered?	Yes	X No			
If Yes provide deta	ails in Genera	l Remarks.		_				
Roads								
X Made up road	Unmade road	d Partly	completed r	new road	Pedestrian a	access only	Adopted	Unadopted

General Remarks
This is an attractive flat located within a popular residential area.
Essential Repairs
None required.
Estimated cost of essential repairs £ Retention recommended? YesX No Amount £

Comment on Mortgageability					
In our opinion, the subject requirements of the chose	s form suitable security for mortgage purposes, subject to any specific leren mortgage provider.	nding			
Valuations					
Buy To Let Cases  What is the reasonable rangmonth Short Assured Tenan	of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT) ? ge of monthly rental income for the property assuming a letting on a 6	£ 130,000 £ 200,000  Yes X No			
	nere there is a steady demand for refited accommodation of this type?	Yes No			
Declaration					
Signed	Security Print Code [542123= 5253] Electronically signed by:-				
Surveyor's name	Gordon Gibb				
Professional qualifications MRICS					
Company name					
Address Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE					
Telephone 01224 571163					
Fax					
Report date	24th April 2025				

# **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

### FLAT C, 33 GROSVENOR PLACE, ABERDEEN, AB25 2RE

Dwelling type: Top-floor flat
Date of assessment: 23 April 2025
Date of certificate: 23 April 2025

Total floor area: 47 m<sup>2</sup>

Primary Energy Indicator: 370 kWh/m²/year

Reference number: 4715-3424-7000-0787-6226
Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst

**Main heating and fuel:** Boiler and radiators, mains

gas


#### You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

# Estimated energy costs for your home for 3 years\*

£2,904

 $^st$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (62)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



# **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (59)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, no insulation (assumed)	****	****
Roof	Pitched, no insulation (assumed)	****	****
Floor	(another dwelling below)	—	_
Windows	Fully double glazed	<b>★★★</b> ☆	<b>★★★★</b> ☆
Main heating	Boiler and radiators, mains gas	<b>★★★</b> ☆	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	<b>★★★</b> ☆	<b>★★★★</b> ☆
Secondary heating	None	_	_
Hot water	From main system	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Lighting	Low energy lighting in 80% of fixed outlets	****	****

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

# The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 65 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.1 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

## Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,412 over 3 years	£2,412 over 3 years	
Hot water	£300 over 3 years	£300 over 3 years	N. 4
Lighting	£192 over 3 years	£192 over 3 years	Not applicable
Totals	£2,904	£2,904	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## **Recommendations for improvement**

None

### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	10,249	(4,954)	N/A	N/A
Water heating (kWh per year)	1,569			

### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Gordon Gibb Assessor membership number: EES/008257

Company name/trading name: Allied Surveyors Scotland Ltd

Address: Marywell House 29-31 Marywell Street

Aberdeen AB11 6JE 01224 571163

Phone number: 01224 571163
Email address: aberdeen@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.